

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141

Revised August 24, 2018

Submit to appropriate OCD District Office

**\*\*In the future, please leave this  
section blank. Much appreciated**

Incident ID	pending	NAB1912958012
District RP	pending	1RP-5475
Facility ID	pending	
Application ID	pending	PAB1912957391

## Release Notification

### Responsible Party

Responsibly Party	Legacy Reserves Operating, LP	OGRID	240974
Contact Name	Brian Cunningham	Contact Telephone	432-234-9450
Contact Email	bcunningham@legacyp.com	Incident # (assigned by OCD)	
Contact Mailing Address	303 W. Wall St. Midland, TX 79701		

### Location of Release Source

Latitude 32.422908 Longitude -103.400565  
(Nad 83 in decimal degrees to 5 decimal places)

Site Name	San Simon 6 State Battery **	Site Type	Tank Battery
Date Release Discovered	04/08/19	API# (if applicable)	N/A 30-025-26949**

AB

Unit Letter	Section	Township	Range	County
** "H"	6	22S	35E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls)	157	Volume Recovered (bbls)	0
<input type="checkbox"/> Produced Water	Volume Released (bbls)		Volume Recovered (bbls)	
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<input type="checkbox"/> Condensate	Volume Released (bbls)		Volume Recovered (bbls)	
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)		Volume Recovered (Mcf)	
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)		Volume/Weight Recovered (provide units)	

Cause of Release

The release was attributed to a hole developing in the oil storage tank.

State of New Mexico  
Oil Conservation Division

Incident ID	pending NAB1912958012
District RP	pending 1RP-5475
Facility ID	pending
Application ID	pending AB1912957391

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Greater than 25 bbls.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means? (phone, email, etc)? Yes, Clyde Wilhoit, Jim Griswold/NMOCD District 1 Spills, 4/8/2019 @ 5:20, Phone Message	

**Initial Response**


*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Release materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11 (A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Clyde Wilhoit  
 Signature:   
 email: cwilhoit@legacylp.com

Title: Maintenance Foreman  
 Date: 4-11-19  
 Telephone: 432-425-4137

**OCD Only**

Received by: 

Date: 5/9/2019