

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27106

Release Notification and Corrective Action

NMLB1122852054

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact <input type="checkbox"/> Jerry Chaney
Address P. O. Box 250		Telephone No. <input type="checkbox"/> 575-748-7446
Artesia, NM 88211		
Facility Name Todd 27P Fed #16 SWD		Facility Type <input type="checkbox"/> SWD

Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>
---------------	---------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section 27	Township T23	Range 31E	Feet from the 330	North/South Line South	Feet from the 330	East/West Line East	County Eddy County
-------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	-----------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 70 BPW	Volume Recovered <input type="checkbox"/> 45 BPW
Source of Release Flowline leak	Date and Hour of Occurrence 7-25-2011 10:30 AM	Date and Hour of Discovery <input type="checkbox"/> 7-25-11 2:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade (OCD) 9:50 AM 7-26-11 Jim Amos (BLM) 7:45 AM 7-26-11	
By Whom? <input type="checkbox"/> Ruben Garcia, Lease Operator	Date and Hour <input type="checkbox"/> See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Buried 3" Fiberglass injection line. Water spotted on surface by roustabout crew passing by.

Describe Area Affected and Cleanup Action Taken.*

Called vacuum truck to pick up water shut lease in and took soil samples. Waiting for soil samples to go forward with remediation. Will replace section of flowline that the leaks keeps occurring at.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: : <u>Adrienne Verkler</u>		OIL CONSERVATION DIVISION	
Printed Name: Adrienne Verkler		Approved by <u>[Signature]</u>	
Title: Field Tech II		Approval Date: <u>AUG 16 2011</u>	Expiration Date:
Date: 7-27-2011 Phone: (575) 748-0174		Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>9/16/2011</u>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-852

Comply * MCLB1122852971