District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised August 1, 2011
Submit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-38142

Release Notification and Corrective Action

nMLB/122939663 258462						OPERATOR				Initial Report				
			EYCO, LLC		Contact; Keith Cannon									
Address; P.0			02		Telephone No. 575-626-1936									
Facility Nan	ne; AID S'	TATE #8]	Facility Type; Oil Tank Battery									
Surface Own	ner; State		Mineral C)wner; S	; State Le				ease No. K-3630-2					
				LOCA	TION	OF REI	LEASE				-			
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/W	est Line	County				
A	13	17S	28E	990	North		330	East		Eddy				
Latitude 32.840325° N Longitude 104.121932° W														
	NATURE OF RELEASE													
Type of Relea							ime Recovered, N/A							
Source of Rel	ease					and Hour of Discovery /2011								
Was Immedia	Was Immediate Notice Given? If YES, To Whom?													
By Whom? Date and Hour														
Was a Watero	ourse Reac		Date and Hour If YES, Volume Impacting the Watercourse.											
}			, Colonia Impacing the Prairie Collins.											
. If a Watercou	rse was Imp	pacted, Descri	be Fully.*			<u> </u>								
	Describe Cause of Problem and Remedial Action Taken* Lighting hitting fiberglass water tank. Burnt tank, No oil tanks effected. Tank was empty prior to fire													
England manage moorgano water tails. Durin tails, 110 on tails effected. Tails was empty prior to life										RECEIVED				
Describe Area								AUG 5 2011						
Remove tanks from dyke, Reline dyke, clean oil tanks, re-build tank battery										NMOCD ARTESIA				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand t														
				d/or file certain re										
public health	or the envir	onment. The	acceptanc	e of a C-141 repo	rt by the	NMOCD ma	arked as "Final Re	eport" do	es not reli	eve the oper	ator of	liability	y	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
federal, state, or local laws and/or regulations.														
	//		OIL CONSERVATION DIVISION											
Signature: /	\TL (Signed By Mile Brance											
Printed Name: Keith Cannon						Approved by District Supervisor:								
Title: Drilling Superintentdent						Approval DateAUG 1 7 2011 Expiration Date:								
E-mail Addres	s: kcannon	@heycoenerg	y.com			Conditions of	Approval:				_			
							Attached L							
Date: 8/3/201 Attach Additi	" - CIRMIT VEVI													
Augui Augiti	onai Shee	11 11CCSS8	1 y		Guid pRA	POSAL NO	T LATER THAN	l:	/	JR1	کر ل	350	8.	