District I
1625 N. French Dr., Hobbs, NM 88240
District II.
1301 W. Grand Avenue, Artesia, NM 88210
District III.
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED
FEB 2 8 2012
NMOCD ARTESIA

Form C-141 October 10, 2003

MOCD ARTESIA

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

Release Hountauon and Corrective Action													
nMLB/2				OPERATOR Initial Report Fin						Final Report			
Name of Company: Linn Operating 269324						Contact: Joe Hernandez							
Address: 21				Telephone No.: 575-738-1739									
Facility Nar	ne: Skelly			Facility Type: Oil well									
Surface Own	ner: BI M		umer	r: BLM API No.: 3001529224									
Surface Own	IICI. DLIVI		WIICI.	. DEIVI ATT 110 3001323224									
				LOCA	TIO	N OF REI	LÈASE						
Unit Letter M							h/South Line Feet from the South 1285		East/West Line West		County Eddy		
Latitude: 32.812954554677 Longitude: -103.844699471996													
				NĂT	URE	OF REL	EASE						
Type of Relea			Volume of Release: 20 / 1 Volume Recovered: 10 / 0										
Source of Rel	lease: Poly	Pipeline	•	Date and Hour of Occurrence: Date and Hour of Discovery:									
Was Immedia	An Madina C	Niver 2		1/5/2012 3:00pm									
was immedia	, .	If YES, To Whom? Mike Burton- BLM											
By Whom? D	anny Homi	er / Able w/H	Date and Hour 01/06/2012										
Was a Watero	course Reac	hed?		If YES, Volume Impacting the Watercourse.									
If a Watercou	rse was Imi	nacted Descri	he Fully *			<u>.L</u>				· · · · · · · · · · · · · · · · · · ·			
If a Watercourse was Impacted, Describe Fully.*:													
Describe Cause of Problem and Remedial Action Taken.*: Drove down road and found leak on three inch flowline, oil leaked over area 20'x 20'													
Describe Area Affected and Cleanup Action Taken.*: Remedial action pending													
Describe Area	i Affected t	ina Cicanap i	ction rak	en. , Remediai a	ction pe	alding							
												1	
I haraby carti	fir that the in	nformation gi	van abova	is true and compl	ate to th	a boot of my	lenovyladao and w	adaratana	l that mare	uant to NIM	OCD mi	log and	
				d/or file certain re									
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
rederal, state,	or local law	vs and/or regu	auons.				OIL COM	TEN A	TION	DIVICIO	NT.		
							OIL CONSERVATION DIVISION Signed By Diversion						
Signature:	if it for	lemon's	organica by r 1171 Assertances										
6.7	, ,	Approved by District Supervisor:											
Printed Name: Joe Hernandez													
Title: Production Foreman							Approval Date: Expiration Date:						
E-mail Addre	cc: iharnana	laz@linnanar	w.com		1.	Conditions of	Ammouali		٠	Assabad			
Date: 1/9/201			COMMINIONS OF	Approvat:	ıles &		Attached	ш					
Attach Addit			ione: 575-	2 1 p 2 1 2 p	F	Remediation	n per OCD Ru	ATION					
/ tudit			<i>J</i>		Guid	elines. SU	BMIT REMED		•	2RP	- 11	753	
					PRΩ	POSAL NO	T LATER THA	N:	0	XIUI	10	· • • • • • • • • • • • • • • • • • • •	
						1111	2012					•	