


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company -- Quantum Resources Management, LLC	Contact Garrett Newton	
Address 1905 West Sears Ave., Artesia, New Mexico 88210	Telephone No. 575-513-0230	
Facility Name Artesia Battery 1 to Battery 3 Transfer Line	Facility Type	
Surface Owner	Mineral Owner	Lease No. API # 30-015-01747 2RP-775 <i>ART UT 22</i>

#### LOCATION OF RELEASE

Unit Letter K	Section 35	Township 17S	Range 28E	Feet from the 2187'	North/South Line FSL	Feet from the 2310'	East/West Line FWL	County EDDY
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	----------------

Latitude 32.79069 N Longitude -104.14837 W

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered -0-
Source of Release Water Transfer Line	Date and Hour of Occurrence 4/29/11 2:00 pm	Date and Hour of Discovery same
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD / Mike Bratcher	
By Whom? Garrett Newton	Date and Hour 4/29/11 2:15 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* The water transfer line coming from the Artesia Battery No. 1 to the Artesia Battery No. 3 was found to be leaking. The line was shut in, repaired, analytical testing was completed and the impacted soil was transported to Lea Land, LLC for disposal.

Describe Area Affected and Cleanup Action Taken.\*

Talon/LPE was contracted for the correction of this release. The impacted area from this release was excavated to a depth of 7-feet deep. A 20 mil liner was installed into the bottom of the excavation. The excavation was backfilled to grade using new material from Lea Land, LLC and contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Garrett Newton</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Garrett Newton	Signed By <i>Mike Bratcher</i> Approved by District Supervisor:	
Title: Field Supervisor	Approval Date: <b>MAR 06 2012</b>	Expiration Date: <i>N/A</i>
E-mail Address: gnewton@pvtnetworks.net	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/> <i>2RP-775</i>
Date: 2/21/2012 Phone: 575-513-0230		

\* Attach Additional Sheets If Necessary

*NMLB 1112932046*