# OPERATOR'S COFY

Fo (A)

L'RECE	Έij	h "	ì	e*	3.
FORM APPROVED					
OM R No 1004-0137					
X 4 L 31 7/07					

Form 3160-5 (April 2004)  DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE- Other instructions on reverse side.  1 Type of Well Gras Well Other  2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC				FORM APPROVED OMENSO 1004-0137 S. Lease Senal No NMNM-106718 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No  S. Welt Name and No TAYLOR DEEP 12 FED #10 9. API Well No 30-025-39468				
3a. Address PO BOX 1936 ~ ROSWELL NM 88202-1936 575/623/6601					10 Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Sec., T 400' FNL & 380' FEL, Sec. 12:		DICATE NATUR	Wilde	11. County of Eddy, N	or Pansh, State  ice Mexico  OTHER DATA	! <b>'</b>		
TYPE OF SUBMISSION			E OF ACTION	,				
If the proposal is to deepen direct Attach the Bond under which the following completion of the inve- testing has been completed. Fin- determined that the site is ready! BLM Bond No. NMB00520 Surety Bond No. B004230 11/1/11 TD, Hole Size 7 7/8	Alter Casing Casing Repair Casing Repair Change Plans Convert to Injection Deraution (clearly state all perturent tourist) or recomplete horizontally, go work will be performed or provide the operations. If the operation result Ahandonment Notices shall be filed for final inspection.)	ve subsurface location to Bond No on tile wills in a multiple compi only after all requirer	is and measured and tr nith BLM/BLA. Requir- tetion or recompletion ments, including reclan mit Lead-800 sks Cl	my proposed wo see vertical depth red subsequent n in a new interva aution, have been	s of all pertunent markers and zones sports shall be filed within 30 days , a Form 3160-4 shall be filed once n completed, and the operator has +10% Bentonite+3%FL-10+5%	· .		
14 Thereby certify that the foreg	oing is true and correct		10	VO/	Anno I	:		
Name (Printed/Typed)	ome i i adeana correct	],,,, =		<u> </u>				
Tammy KV Link	11/0.1/	little Pi	roduction Tech					
Signature	OK. Leave	Date		11/03/2011				
	THIS SPACE FOR FE	DERAL OR S	TATE OFFICE	USE		:		
Approved by Conditions of approval, if any, are at	tuched Approval of this notice does		ıtie		)aic			

Conditions of approval, it any, are statement. Approval of this notice does not warrant of certify that the applicant holds legal or equitable rule to those nights in the subject lease which would entitle the applicant to conduct operatures thereon.

Title 18 U.S.C. Section 1001 and Title 45 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, licitious or fraudulent statements or representations as to anymatter within its jurisdiction.

(Instructions on page 2)

## SUMMARY CASING AND CEMENTING REPORT

STRING: PRIMARY DATE: 11/1/2011

OPERATOR: NADEL & GUSSMAN HEYCO WELL: TAYLOR 12 FED #10

CONTRACTOR: PATRIOT RIG: #1
REP: KEITH CANNON

CASING DETAIL

HOLE SIZE: 7.875" DEPTH: 5500

5.5" HOLE 5500.00 5 5" FLOAT SHOE 0.90

5499.10 2 JT. 5.5" J-55 17 # CASING 84.34

5414.76 5.5" FLOAT COLLAR 0.80

5.5" FLOAT COLLAR <u>0.80</u> 5413.96

127 JTS 5.5"J-55 17# CASING <u>5403.10</u> 10.86

KB TO GL 18.00

CENTRALIZERS PLACED @ 1 ON EACH SHOE JT. NEXT 23 EVERY OTHER JT.

#### REMARKS

TOTAL CASING DELIVERED....132 JTS (5617.51) 5 1/2" 17# J-55 LTC ALL CASING WAS DRIFTED, CLEANED, & VISUALLY INSPECTED ON LOCATION.

. CIRCULATED CAPACITY & ANNULAR VOLUME

### **EXCESS CASING**

CASING NOT USED ....3 JTS. 126.57' 5 1/2" 17# J-55 LTC

DISPOSITION .... GYS YARD

### CEMENTING DATA

COMPANY: RISING STAR DISTRICT: HOBBS

### **IST STAGE:**

PREFLUSH: 20bbls F/W SPACER

**LEAD:** 800 SKS CLASS "C" 50/50+10%BENTONITE+.3%FL-10+5%SALT(BWOW)+ 25%R-38

<u>TAΠ.:</u> 200 SKS STARBOND C+.3%FL-10+.1%C-20± 25%R-38

# SUMMARY CASING AND CEMENTING REPORT

NOTE:

Plug down @ 12:30am 10/29/2011. Did not circulate cement. Had 1700 psi of lift just before plug was scated w/ 123 bbls

Page 2 of 2 11/3/2011