18-40026

	6, R28E, Unit N, 360 FSL, 2280	FWL. Eddy County
		, ,
ERATOR Lime Rock Reso	urces	
LLING CONTRACTOR	United Drilling, Inc.	
-		
The undersigned hereby cert	ifies that he is an authorized repr	resentative of the drilling contractor
drilled the above described v	well and had conducted deviation	test and obtained the following
ılts:		
Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
0° @ 197'	1.6° @ 2283'	**************************************
0° @ 445'	1.7° @ 2377'	
2.6° @ 616'	1.5° @ 2470'	
3.8° @ 679'	1.6° @ 2564'	
4.6° @ 741'	8° @ 2658'	
6.6° @ 804'	.9° @ 2753'	
8.2° @ 865'	9° @ 2847'	
7.3° @ 991'	8° @ 2941'	
8.8° @ 1086'	.7° @ 3413'	
8.4° @ 1180'	.8° @ 3601')
7.6° @ 1275'	5° @ 3696'	
7.5° @ 1306'	.7° @ 3790'	
6.9° @ 1432'	.6° @ 4167'	
5.8° (a) 1495'	4° @ 4261'	
4.4° (a) 1558'	3° @ 4544'	
<u>4.7° @ 1621'</u>		
	Drilling Contractor-	UNITED DRILLING, INC.
	_	Lune Dalian
	By:	Juan Hirriga
		(Luisa Noriega)
	Title:	Asst. Office Manager
Subscribed and over	ome to before we this 7/4/	-
Subscribed and Swe	orn to before me this <u>do</u> day	01 <u>Numer1</u> , 2012.
		(1 M
		Willes I factor
•		Notary/Public
		(Mayes Wa) There
My Commission Expires: /		