

RECEIVED
APR 5 2012
NMOCD ARTESIA

District I
 1625 N. French Dr., Hobbs, NM 88240
District II
 1301 W. Grand Avenue, Artesia, NM 88210
District III
 1000 Rjo Brazos Road, Aztec, NM 87410
District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

NMLB 1210941467

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	White Oak State #1	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	
		Lease No. (API#)	30-015-29749



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	23	17S	28E					Eddy

Latitude 32.8150 Longitude 104.1392

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	18bbls
Source of Release	Water tank	Date and Hour of Occurrence	03/25/2012	Date and Hour of Discovery	03/25/2012 4:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Water tank ran over due to loss of power at the facility. CVE returned power.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls were released from the water tank and we were able to recover 18bbls with a vacuum truck. The fluids released inside the dike area and measured and area of roughly 5' x 30'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will submit a work plan for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By 	
Title:	HSE Coordinator	Approved by District Supervisor:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	APR 18 2012
Date:	04/05/2012	Expiration Date:	
Phone:	432-212-2399	Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per OCD Rules &
 Guidelines. **SUBMIT REMEDIATION
 PROPOSAL NOT LATER THAN:**

2 RP-1096

* Attach Additional Sheets If Necessary