

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

RECEIVED

APR 11 2012

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NMLB 12/15 33555

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit #186	Facility Type E&P

Surface Owner State Of N.M.	Mineral Owner State of N.M.	Lease No. 8910000303E
-----------------------------	-----------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter K	Section 32	Township 23S	Range 30E	Feet from the 1750	North/South Line South	Feet from the 1650	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.258800 Longitude W 103.906800

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 5 bbls produced water and 5 bbls crude oil	Volume Recovered: 0
Source of Release: a valve on the wellhead	Date and Hour of Occurrence 4/9/12 Time unknown	Date and Hour of Discovery 4/9/12 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\* A valve on the wellhead cracked, the valve was replaced.

Describe Area Affected and Cleanup Action Taken.\* An area covering approximately 850 sq. ft. on the caliche well pad was affected by the release, all of the product had soaked into the ground, the impacted areas will be excavated and sampled on 4/11/12. The spill will be remediated following the NMOCD guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By: [Signature]	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: APR 24 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/10/12 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 5/24/2012	

\* Attach Additional Sheets If Necessary

2RA-1101