

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15:29 NMAC.

Release Notification and Corrective Action

nmlb12/3129035 *240974* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Legacy Reserves Operating LP	Contact	Berry Johnson
Address	P.O. Box 10848 Midland, TX 79702	Telephone No.	432-689-5200
Facility Name	South Red Lake II	Facility Type	Injection Line
Surface Owner	Mineral Owner	API No. <i>30-015-00667</i>	

LOCATION OF RELEASE

Nearest Legacy well: SRL #41 #11
G-36-17s-27E


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
		17S	27E					Eddy

Latitude *32.79080830* Longitude *104.23183501*

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	25-30 bbls.	Volume Recovered	0
Source of Release	Injection line	Date and Hour of Occurrence	4/13/12 - 12:00 Noon	Date and Hour of Discovery	4/13/12 - 12:00 Noon
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike B. w/ OCD		
By Whom?	David Adkins w/ Talon	Date and Hour	4/13/12 - 12:00 Noon		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The paved road was cut in order to pull injection line with the old casing from beneath. All contaminated dirt was picked up and replaced with fresh dirt. New casing and new 2" injection line was installed and the road was back-filled to Eddy County specification. All contained dirt was hauled to disposal site. Talon checked for chlorides during this process. The water table was never compromised.

Describe Area Affected and Cleanup Action Taken.*

Same as above.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Berry Johnson*
Printed Name: Berry Johnson
Title: Operations Superintendent
E-mail Address:
Date: 04/18/12 Phone: 432-689-5200

Signed By *[Signature]*
Approved by Environmental Specialist:

Approval Date: *MAY 10 2012* Expiration Date:

Conditions of Approval:
Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION**
PROPOSAL NOT LATER THAN:
6/10/2012

Attached ☐

* Attach Additional Sheets If Necessary

2RCP-1118