



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NMLB 12575315 OPERATOR (147179) ☒ Initial Report ☐ Final Report

Name of Company: Chesapeake Operating, Inc.	Contact: Bradley Blevins
Address: 1616 West Bender, Hobbs, NM 88240	Telephone No.: (575) 391-1462, ext. 86424
Facility Name: Old Indian Draw #24	Facility Type: Pipeline

Surface Owner:	Mineral Owner:	API No.: 3001522101
----------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter O	Section 7	Township 22S	Range 28E	Feet from the 330	North/South Line South	Feet from the 2283	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N32° 24' 02.35"

Longitude: W104° 07' 43.71"

NATURE OF RELEASE

Type of Release: Oil and water mix	Volume of Release: 47-bbls	Volume Recovered: 40-bbls
Source of Release: check valve failed	Date and Hour of Occurrence: 4/27/12 @ 09:00 hrs	Date and Hour of Discovery: 4/27/12 @ 09:00 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD	
By Whom? Bradley Blevins	Date and Hour: 4/27/12	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Depth to Groundwater: ~ 50 feet

Describe Cause of Problem and Remedial Action Taken.\* Check valve failed releasing 2 bbls oil and 45 bbls water with 40 total bbls recovered.

Describe Area Affected and Cleanup Action Taken.\* Approximately 6,620 square feet of area was affected by the release of ± 47-bbls of oil and water. ± 40-bbls of oil were recovered from the site. An Emergency-Response Team arrived at the release area and began continuous abatement of the impacted area. Standing liquid was scrapped up and hauled away for disposal at a state approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By: <u>Mike Blevins</u>	
Title: EH & S Field Specialist	Approved by District Supervisor:	
E-mail Address: bradley.blevins@chk.com	Approval Date: JUN 05 2012	Expiration Date:
Date: 5-11-2012 Phone: (575) 391-1462, #86424	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

4/5/12 Operator has completed  
Clean up

2RP-1150