



District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB1215753175 OPERATOR 147179 ☐ Initial Report ☒ Final Report

Name of Company: Chesapeake Operating, Inc.	Contact: Bradley Blevins
Address: 1616 West Bender, Hobbs, NM 88240	Telephone No.: (575) 391-1462, ext. 86424
Facility Name: Old Indian Draw #24	Facility Type: Pipeline

Surface Owner:	Mineral Owner:	API No.: 3001522101
----------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	7	22S	28E	330	South	2283	East	Eddy

Latitude: N32° 24' 02.35"

Longitude: W104° 07' 43.71"

NATURE OF RELEASE

Type of Release: Oil and water mix	Volume of Release: 47-bbls	Volume Recovered: 40-bbls
Source of Release: check valve failed	Date and Hour of Occurrence: 4/27/12 @ 09:00 hrs	Date and Hour of Discovery: 4/27/12 @ 09:00 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD	
By Whom? Bradley Blevins	Date and Hour: 4/27/12	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		

Depth to Groundwater: ~ 50 feet

Describe Cause of Problem and Remedial Action Taken.* Check valve failed releasing 2 bbls oil and 45 bbls water with 40 total bbls recovered.

Describe Area Affected and Cleanup Action Taken.* Approximately 6,620 square feet of area was affected by the release of ± 47-bbls of oil and water. ± 40-bbls of oil were recovered from the site. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Standing liquid was scrapped up and hauled away for disposal at a state approved facility. Approximately 230 yds of contaminated soil was excavated and hauled for disposal. Analytical data from samples taken demonstrated vertical delineation had reached threshold goals. With EMNRD approval approximately 240 yds of clean caliche was brought in and site backfilled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By: <u>Mike Brannan</u>	
Title: EH & S Field Specialist	Approved by District Supervisor:	
E-mail Address: bradley.blevins@chk.com	Approval Date: JUN 05 2012	Expiration Date: N/A
Date:	Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/>
Phone: (575) 391- 1462, #86424		

* Attach Additional Sheets If Necessary

2RP-1150