District I 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. 1st Street, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

> Oil Conservation Division. 1220 South St. Francis Dr. Santa Fe NM 87505

RECEIVED Form C-141
Revised October 10, 2003

JUN 13 2030bmit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

NMOCD ARTESIA

Release Notification and Corrective Action Mame of Company OGRID Number Contact							
Name of Company Yates Petroleum Corporation 25575 Address 105 S. 4 TM Street 105 S. 4 TM Street 105 S. 4 TM Street 106 S. 4 TM Street 107 Sourial Street 108 Sourial Street 109 Sourial Street 109 Sourial Street 100 Souria							
Name of Company Yates Petroleum Corporation 25575 Amber Cannon Amber Cannon Address Telephone No. 575-748-1471 Facility Name API Number 30-015-21940 Battery 30-015-21940 Battery	Report						
Telephone No. S75-748-1471							
Strice S							
Facility Name Hawkins GY #1 Battery							
Surface Owner Fee Mineral Owner Fee Mineral Owner Fee Mineral Owner Fee Lease No.							
Surface Owner Fee LOCATION OF RELEASE Unit Letter C							
Township 18S Section 1							
Location of Release							
Unit Letter C Section 27 Township 18S 26E Feet from the North North Feet from the 1830 East/West Line West Eddy Latitude 32.72486 Longitude 104.37212 NATURE OF RELEASE Type of Release Produced Water / Gas 7 B/PW; 8 MCF 6 B/PW Source of Release Date and Hour of Occurrence 1/30/2012 1/30/2012 1/30/2012 Was Immediate Notice Given? Date and Hour of Occurrence 1/30/2012 1/30/2012 1/30/2012 Was Immediate Notice Given? Date and Hour N/A By Whom? N/A Was a Watercourse Reached? Date and Hour N/A Was a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results above the RRAL a work plan will be submitted to the OCD Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results; Yates Petroleum requests closure.							
Latitude 32.72486 Longitude 104.37212 NATURE OF RELEASE Type of Release Produced Water / Gas Volume of Release 7 B/PW; 8 MCF 6 B/PW Source of Release Obstace 1/30/2012 1/30/2012 1/30/2012 Was Immediate Notice Given Via More Not Required N/A By Whom? N/A Was a Watercourse Reached? If Yes No Not Required N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results. Yates Petroleum requests closure.							
Latitude 32.72486 Longitude 104.37212 NATURE OF RELEASE Type of Release Produced Water / Gas Volume of Release Produced Water / Gas Volume of Release Produced Water / Gas Once of Release Produced Water / Gas Date and Hour of Occurrence Date and Hour of Discovery Date and Hour of Occurrence Date and Hour of Discovery Date and Hour of Occurrence Date and Hour of Discovery Date and Hour of Discovery N/A By Whom? N/A Was a Watercourse Reached? Date and Hour N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results. Yates Petroleum requests closure.							
Type of Release Produced Water / Gas Produced Water / Gas Produced Water / Gas Produced Water / Gas Source of Release Gas/Water flow lines Gas/Water flow lines Was Immediate Notice Given? Was Immediate Notice Given? Was a Watercourse Reached? If YES, To Whom? N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. M/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING Is 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Type of Release Produced Water / Gas Produced Water / Gas Produced Water / Gas Produced Water / Gas Source of Release Gas/Water flow lines Gas/Water flow lines Was Immediate Notice Given? Was Immediate Notice Given? Was a Watercourse Reached? If YES, To Whom? N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. M/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING Is 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Type of Release Produced Water / Gas Source of Release Gas/Water flow lines Date and Hour of Occurrence 1/30/2012 Was Immediate Notice Given? Wes Not Required No Not Required Date and Hour of Occurrence 1/30/2012 If YES, To Whom? N/A By Whom? N/A Was a Watercourse Reached? If yes No Not Required If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines wer repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results 1PH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Type of Release Produced Water / Gas Source of Release Gas/Water flow lines Date and Hour of Occurrence 1/30/2012 Was Immediate Notice Given? Wes Not Required No Not Required Date and Hour of Occurrence 1/30/2012 If YES, To Whom? N/A By Whom? N/A Was a Watercourse Reached? If yes No Not Required If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines wer repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results 1PH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Source of Release Gas/Water flow lines Date and Hour of Occurrence 1/30/2012 1/30/2012 Was Immediate Notice Given? Yes No Not Required No							
Gas/Water flow lines 1/30/2012 1/30/2012 Was Immediate Notice Given?							
Was Immediate Notice Given? Yes No Not Required If YES, To Whom? N/A							
By Whom? N/A Was a Watercourse Reached? Yes No No N/A If YES, Volume Impacting the Watercourse. N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines wer repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
N/A Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Describe Cause of Problem and Remedial Action Taken.* Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Gas and water flow lines were leaking. Wells, tubing and casing were shut off. A vacuum truck was called to recover released water. Flow lines were repaired. Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.	ro						
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10' (SW corner of battery). Impacted soils have been excavated and hauled to an approved NMOCD disposal facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.	16						
Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results a above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (85', Section 27, T18S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.							
Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on impacted soils being excavated and hauled NMOCD approved facility and analytical results, Yates Petroleum requests closure.	arc						
	to a						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and							
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger							
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	v						
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human hea							
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other							
federal, state, or local laws and/or regulations.							
OIL CONSERVATION DIVISION							
Signature: () mbox Cammo							
Approved by District Business Briston 11/4 Business							
Printed Name: Amber Cannon							
Title: Senior Environmental Regulatory Agent Approval Date UL 1 7 2012 Expiration Date: LA							
E-mail Address: acannon@yatespetroleum.com Conditions of Approval: Attached							

2RP-1016

Phone: 575-748-4111

Date: Tuesday, June 12, 2012

^{*} Attach Additional Sheets If Necessary