


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

**Operator** ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Chicken Hawk State #1	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-33682

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	15	25S	28E					Eddy

Latitude 32 08.236 Longitude 104 04.079

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	85bbls	Volume Recovered	80bbls
Source of Release	Produced water tank	Date and Hour of Occurrence	06/26/2012	Date and Hour of Discovery	06/26/2012 8:40 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	6/26/2012 3:12 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The produced water tank at the Chicken Hawk State Tank Battery overflowed due to an electrical problem that did not allow the high level alarm to be sent out. Electricians have been called out to the facility to correct the problem.

Describe Area Affected and Cleanup Action Taken.\*

Initially roughly 85bbls of produced water was released from the water tank and we were able to recover 80bbls with a vacuum truck. The entire release was completely contained inside the dike walls of the tank battery. The spill area measured approximately 20' x 40'. BBC International Inc. will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By: Mike Bratcher
Title:	HSE Coordinator	Approval Date:	JUL 12 2012
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	06/29/2012	Phone:	432-212-2399
Conditions of Approval:		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

8/12/12

2RP-1213