

RECEIVED

JUL 05 2012

NMOCD ARTESIA

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1219453469

OPERATOR☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Choctaw 3" Water Line	Facility Type	3" Water Line

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-36351
			Closest well location

LOCATION OF RELEASE

Willow St #9

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	17S	31E					Eddy

Latitude 32 49.742 - Longitude 103 52.417

NATURE OF RELEASE

Type of Release	Produced water / Skim oil	Volume of Release	80bbls	Volume Recovered	75bbls
Source of Release	3" poly water line	Date and Hour of Occurrence	06/29/2012	Date and Hour of Discovery	06/29/2012 7:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	06/30/2012 6:50 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A new 3" poly water line was accidentally left un-fused to the existing water line while replacing poly that had been burned by a fire earlier in the month. The un-fused poly line released fluid onto the previously burned area in the pasture north of the Yucca/Willow Tank Battery. We have fused the poly lines together and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Initially 80bbls were released from the 3" poly line and we were able to recover 75bbls with a vacuum truck. The release occurred north of the Yucca/Willow Tank Battery in the pasture measuring approximately 3' x 100'. All free fluid has been recovered. BBC International will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 
Printed Name: Josh Russo
Title: HSE Coordinator
E-mail Address: jrusso@conchoresources.com
Date: 07/05/2012 Phone: 432-212-2399

OIL CONSERVATION DIVISIONApproved by District Supervisor: Signed By 

Approval Date: JUL 12 2012

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/12/12

2RP-1220