

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1221437921

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	873	Contact Natalie Gladden
Address PO Box 1849 Eunice, NM 88231		Telephone No. 575-390-4186
Facility Name Washington 33 Battery (Washington 33 #36)		Facility Type Production Facility
Surface Owner BLM	Mineral Owner	API No. 30-015-39886

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	33	17S	28E	2310	FNL	1650	FEL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/Produced Water	Volume of Release 60	Volume Recovered 55
Source of Release Electrical Power Failure	Date and Hour of Occurrence 07/11/12	Date and Hour of Discovery 07/11/12
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	RECEIVED JUL 19 2012 NMOCD ARTESIA
By Whom? Natalie Gladden	Date and Hour 07/11/12 429PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Main power was shut off to the drive that controls the transfer pumps that dispose of the water, causing the tanks to overflow.		
Describe Area Affected and Cleanup Action Taken.* Vacuum truck was dispatched to recover standing fluid and one-call was placed. A new alarm system has been installed. NMOCD Regulations will be followed to closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION Signed By <i>[Signature]</i>	
Printed Name: Natalie Gladden	Approved by Environmental Specialist:	
Title: EHS Environmental Tech	Approval Date: AUG 01 2012	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/16/12	Phone: 575-390-4186	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

9/1/12

2RP-1236