


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1225653954

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Cimarex Energy <i>162683</i>	Contact	Terry D. Ainsworth
Address	600 Marienfeld Midland, TX 79701	Telephone No.	(575) 390-1388
Facility Name	Grynberg 11 Fed Com 3	Facility Type	Oil Well
Surface Owner	Mineral Owner	Lease No.	NM 14468

LOCATION OF RELEASE

API#30-015-34/93

Unit Letter	Section 11	Township 25S	Range 26E	Feet from the 1500	North/South Line South	Feet from the 1300	East/West Line West	County Eddy
-------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	61 bbls	Volume Recovered	60 bbls
Source of Release	Water tank ran over	Date and Hour of Occurrence	8/31/2012 5AM	Date and Hour of Discovery	8/31/2012 8AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water hauler failed to haul PW Called for a vacuum truck and picked up all we could

Describe Area Affected and Cleanup Action Taken.*

The entire spill was contained inside the lined berm We will pick up contaminated gravel and haul to Lea Land Farm and inspect liner for holes (I think this one held)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Terry D. Ainsworth		Approved by District Supervisor:	Signed By <i>Mike Brannon</i>
Title: Production Foreman	Approval Date: SEP 12 2012	Expiration Date:	
E-mail Address: tainsworth@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 9/1/2012 Phone: 575-390-1388	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:		

* Attach Additional Sheets If Necessary

October 12th, 2012

2RP-1290