

UNITED STATES

N.M. Oil Cons. DIV-Dist. 2

DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT1001 W. Grand Avenue  
Artesia, NM 88210FORM APPROVED  
OMB NO. 1004-0135  
Expires January 31, 2004

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an  
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

## 1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

## 2. Name of Operator

BP America Production Company

## 3a. Address

P.O. Box 1089 Bmice NM 88231

## 3b. Phone No. (include area code)

505.394.1649

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL H, 1980' FNL &amp; 660' FEL

SECTION 1, T21S, R21E

SENE

RECEIVED

MAY 06 2005

OCD-ARTESIA

## 5. Lease Serial No.

NM27451

## 6. If Indian, Allottee or Tribe Name

## 7. If Unit or CA/Agreement, Name and/or No.

## 8. Well Name and No.

NASSER FEDERAL 1

## 9. API Well No.

30.015-27865

## 10. Field and Pool, or Exploratory Area

INDIAN LOAFER DRAW UPPER  
PENN/LB CANYON MORROW

## 11. County or Parish, State

EDDY NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

- ☒
- Notice of Intent
- 
- ☐
- Subsequent Report
- 
- ☐
- Final Abandonment Notice

## TYPE OF ACTION

- |  |   |  |   |
|--|---|--|---|
| <input type="checkbox"/> Acidize                 | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing            | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair           | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                | <input type="checkbox"/> Other _____    |
| <input checked="" type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |   |
| <input type="checkbox"/> Convert to Injection    | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |   |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD: 8250' PED: 7988' PERFS: 7862-7868'

APPROVED FOR 2 MONTH PERIOD

ENDING 7/5/05

SCOPE OF WORK: PULL TUBING &amp; REPLACE BAD JT. GIH OE.

MIRUPU. BLEED DOWN TBG &amp; CSG PRESS.

PUMP SUFFICIENT 2% KCL TO PLACE WELL ON VAC.

NDWH. NUBOP. RLK PKR &amp; POH W/TBG. STRAP OUT OF HOLE. LD BAD JTS.

GIH W/2-3/8" SN &amp; TBG. LAND SN @ 7860+/- . PMP SUFFICIENT 2% KCL TO PLACE WELL ON VAC.

NDBOP &amp; NUWH. SWAB AS NECESSARY TO KICK WELL OFF AND TURN TO PRODUCTION

RDFU.

05.01.05: WELL HAD 300 PSI ON TBG &amp; CSG WHEN STARTED. KILLED WELL W/150 BBL 2% KCL WIR. WELL

WILL NOT CIRC. POH W/218 JTS 2-3/8" TBG &amp; 5 PMP JTS, APPROX 6780' OF TBG. FOUND PIPE PARTED.

JOINT # 181 HAD HOLES AND FROM JT 180 DOWN WAS SEVERELY PITTED & CORRODED. RIH W/2500' OF 2-3/8" YELLOW  
BAND TBG AND SHUT DOWN FOR ENRG EVALUATION.

WELL HAS DHC APPROVAL BY NMCD EFFECTIVE 12.16.02. DHC-30880

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Kellie D. Murrish

## Title

Scheduler

Date 05.02.05

APPROVED

MAY - 5 2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

## Approved by

## Title

IFS BABYAK  
PETROLEUM ENGINEERConditions of approval, if any, are attached. Approval of this notice does not warrant or  
certify that the applicant holds legal or equitable title to those rights in the subject lease  
which would entitle the applicant to conduct operations thereon.


## Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United  
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RKB ???  
GL ???

API # 30-015-27865

Spud: 2/27/94  
Completed: 3/31/94



TD: 8250'  
PBTD: 7988'

13 3/8", 54.5#, J-55, ST&C @ 406'  
Cmt w/ 470 sx "C" Did not circ  
Top out w/ 630 sx to surface

9 5/8", 36#, J-55, ST&C @ 1795'  
Cmt w/ 835 sx  
Using 1" dumped 400 sx cmt for TOC @ 880'

2 3/8". 4.7#, N-80 tbg

TOC @ 4800' per CBL

Upper Penn

5772-6380'

7148-7156'

Some type of restriction in tbg about 600' above the packer

Morrow

On-off tool w/ 1.86" profile  
LOK-Set packer @ 7778'

7862-7868' Shot thru tbg 3/25/94

5 1/2", 17#, N-80, LT&C @ 8223'  
Cmt w/ 925 sx  
TOC @ 4800' CBL

**NASSER FEDERAL # 1**  
Indian Loafer Draw

1980' FNL & 660' FEL, Sect 1  
T-21-S, R-21E  
Eddy County, New Mexico

DLT 3/15/05  
Perfs added 4/28/05