

FAUX



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

*Field Inspection Program
"Preserving the Integrity of Our Environment"*

08-Aug-05

MERIT ENERGY CO

PO Box 69

Loco Hills NM 88255

NOTICE OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

FREN OIL COMPANY No.018

K-19-17S-31E

30-015-05264-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/08/2005	Routine/Periodic	Chris Beadle	Yes	No	9/8/2005	iCLB0522042836
Violations						
Surface Leaks/Spills						

Comments on Inspection: Location needs attention. Equipment OK. Wellhead area has heavy contamination, runoff to the south and along road. Remediation required. Location is upslope from natural lake playa. Contact NMOCD District 2 Environmental Compliance Officer to discuss remediation requirements.

TURNER A No.049

G-19-17S-31E

30-015-28837-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/08/2005	Routine/Periodic	Chris Beadle	Yes	No	9/8/2005	iCLB0522050070
Violations						
Surface Leaks/Spills						

Comments on Inspection: Location needs attention. Equipment OK. Contamination at wellhead, chloride and hydrocarbon contamination visible. Runoff from this wellhead contamination has moved across site towards a cattle water tank. Tank is approximately 300 feet east of wellhead, contamination has visibly run off about 100 feet. Remediation required. Contact NMOCD District 2 Environmental Compliance Officer to discuss remediation requirements.

TURNER B No.115

A-20-17S-31E


30-015-30211-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/08/2005	Routine/Periodic	Chris Beadle	Yes	No	9/8/2005	iCLB0522046838
Violations						
Gas Vent/Flare Equipment (Rules 114, 115)						
Surface Leaks/Spills						

Comments on Inspection: Location needs attention. Equipment OK. Produced fluids pooled at wellhead. Contamination has runoff from wellhead to the south and off site impacting pasture. Remediation required. Contact NMOCD District 2 Environmental Compliance Officer to discuss remediation requirements.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.