

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 13 2012

NMOC DISTRICT OFFICE
ARTESIA

Form C-141
Revised October 10, 2003

Appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

01JMW1231955577

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL Keel B 69	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001529820
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	05	17S	31E	2630	SOUTH	2620	WEST	EDDY

Latitude: 32.86349 Longitude: -103.89109

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 15bbls / 5bbls	Volume Recovered: 8bbls / 2bbls
Source of Release: Valve	Date and Hour of Occurrence: 11/08/2012 10:30am	Date and Hour of Discovery: 11/08/2012 11am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NM OCD / Terry Gregston-BLM	
By Whom? Gary Wink	Date and Hour 12/02/2011 9am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: DROVE TO LOCATION DOING DAILY ROUTINE AND NOTICED OIL ON GROUND COMING OUT OF WELL PACKING NOTICE 2" TUBING VALVE CLOSED, (PUMP UNIT WAS TURNED ON AND VALVE WAS NOT OPENED) TURN WELL OFF, CALL VACUUM TRUCK TO DO CLEAN UP.

Describe Area Affected and Cleanup Action Taken.* : OIL RAN W. 90 FT.LONG X 8 FT WIDE. RAN S. 15 FT.LONG X 2 FT.WIDE. RAN E. 90FT LONG X 6 FT WIDE APROX. 20 BBLS WATER AND OIL. ALL FLUID WAS ON PAD. PICKED UP OIL AND WATER OFF OF GROUND AND TOOK IT TO DISPOSAL, ALSO PICKED UP CONTAMINATED DIRT AND PUT IT ON PLASTIC ON SIDE OF LOCATION.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Joe Hernandez*

Printed Name: Joe Hernandez

Title: Production Foreman

E-mail Address: jhernandez@linenergy.com

Date: 11/13/2012

Phone: 575-942-9492

Approved by District Supervisor:

Signed By

Mike Bratcher

NOV 14 2012
Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

Dec. 14 2012

2RP-1401