


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 3 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

0JMW1232155041

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 217955	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Canvasback 13 Federal #2H	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-40538
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	13	24S	31E					Eddy

Latitude 32 14.014 Longitude 103 43.094

NATURE OF RELEASE

Type of Release	Crude oil	Volume of Release	80bbbls	Volume Recovered	75bbbls
Source of Release	Oil tank	Date and Hour of Occurrence	11/08/2012	Date and Hour of Discovery	11/08/2012 9:45 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Josh Russo	Date and Hour	11/12/2012 11:27a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Oil haulers did not pick up their loads of oil at the anticipated time causing the oil tank to overflow at the facility.

Describe Area Affected and Cleanup Action Taken.\*

Initially 80bbbls were released inside the facility and we were able to recover 75bbbls with a vacuum truck. This is a lined tank battery. We have steam cleaned the tanks, catwalk, and liner. Any contaminated gravel has been removed and we have replaced with fresh gravel as needed. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name:

Josh Russo

Title:

Senior Environmental Coordinator

E-mail Address:

jrusso@concho.com

Date:

11/14/2012

Phone:

432-212-2399

Approved by District Supervisor:

NOV 16 2012

Approval Date:

Signed By

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-1409