


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
Appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

njm/130242708

OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Gary Wink
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: H.E. West A Battery- HE West A 29	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001528467
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter H	Section 04	Township 17S	Range 31E	Feet from the 1345	North/South Line North	Feet from the 1194	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.86703 Longitude: -103.86939

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 40 bbls	Volume Recovered: 10 bbls
Source of Release: 3" Circulating line	Date and Hour of Occurrence: 3/30/2013 1:30pm	Date and Hour of Discovery: 3/30/2013 2pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD Mike Burton-BLM	
By Whom? Rick Rickman / Gary Wink	Date and Hour 3/30/2013 2:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Buried 3" circulating line developed a hole causing fluid to leak from the tank, due to corrosion.		
Describe Area Affected and Cleanup Action Taken.* : Vac truck recovered 10 bbls, remove, haul, and dispose, in approved land fill.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary W. Wink</i>	OIL CONSERVATION DIVISION	
Printed Name: Gary W. Wink	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Construction Foreman	Approval Date: APR 12 2013	Expiration Date:
E-mail Address: gawink@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/03/2013 Phone: 575-390-3477	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

2RP-1618
May 12, 2013