


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 1311447152

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	Facility Name Dolores AIL Federal #1	Telephone No. 575-748-1471
Facility Name Dolores AIL Federal #1	API Number 30-015-26547	Facility Type Battery
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65418

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	22S	31E	660'	North	430'	East	Eddy

Latitude 32.39694 Longitude 103.74086

NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release 20 B/PW; 1 B/O	Volume Recovered 0 B/PW; 0 B/O
Source of Release Poly pipe on water line	Date and Hour of Occurrence 4/21/2013; PM	Date and Hour of Discovery 4/21/2013, PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The poly pipe ruptured on main water line. All wells were turned off, tank valves were shut and personnel made sure there was no continuation of a spill. The water line was repaired.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 36'x100' The release was around the tin horn to the east (across the lease road) of the Dolores battery. Some of the released water flowed across the lease road and onto the Dolores Battery production pad. All affected areas will have initial clean-up completed, and all excavated soils will be disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. Depth to Ground Water: >100' (approximately 448', Section 16, T22S-R31E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: *Amber Cannon*
Printed Name: Amber Cannon
Title: Environmental Regulatory Agent
E-mail Address: acannon@yatespetroleum.com
Date: Wednesday, April 24, 2013 Phone: 575-748-4111

Approved by District Supervisor:
Signed By: *Milo Benavidez*
Approval Date: **APR 24 2013** Expiration Date:
Conditions of Approval:
Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**
Attached

* Attach Additional Sheets If Necessary

May 24, 2013
2RP-1635