

API# 30-015-41217

WELL NAME AND NUMBER Eagle 34 E Federal No. 70

LOCATION Section 34, T17S, R27E, Unit E, 2310 FNL, 990 FWL, Eddy County

OPERATOR Lime Rock Resources

DRILLING CONTRACTOR United Drilling, Inc.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and had conducted deviation test and obtained the following results:

Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
.6° @ 163'	.7° @ 4658'	
.9° @ 380'		
.9° @ 657'		
1.8° @ 1139'		
2.4° @ 1392'		
2.2° @ 1482'		
1.7° @ 1578'		
1.6° @ 1831'		
2.7° @ 2086'		
1.2° @ 2249'		
2.2° @ 2394'		
2.0° @ 2494'		
1.5° @ 2584'		
1.3° @ 2838'		
1.5° @ 3090'		
1.5° @ 3598'		

Drilling Contractor- UNITED DRILLING, INC.

By: Luisa Noriega
(Luisa Noriega)

Title: Asst. Office Manager

Subscribed and sworn to before me this 29th day of April, 2013.

Charles New Mexico
Notary Public
County State

My Commission Expires: 10/8/16

