

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*RJM* 1327630022 OPERATOR  Initial Report  Final Report

Name of Company Americo Energy Resources, LLC 22805	Contact Ehsan Bayat	
Address 7575 San Felipe St ste 200 Houston TX 70063	Telephone No. 713-984-9700	
Facility Name East Shugart Unit	Facility Type 11	
Surface Owner	Mineral Owner	API No. 30-015-05695

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	35	18S	31E	2310	North	2310	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release FSW and Skim Oil	Volume of Release 3 bbls	Volume Recovered 1.5
Source of Release pin hole leak pipe esu 11	Date and Hour of Occurrence 9/26/2013 9am	Date and Hour of Discovery 9am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\*  
There was a pin hole leak in the pipe. 3 bbls of water and skim oil. Vac truck came to location, cleaned and remediated

**RECEIVED**  
OCT 02 2013  
NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.\*  
Vac truck came to location, cleaned and remediated \*Soil Sample Required

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ehsan Bayat	Approved by Environmental Specialist: Signed By <i>[Signature]</i>	
Title: Project Evaluator/regulatory Analyst	Approval Date: OCT 03 2013	Expiration Date:
E-mail Address: ehsan.bayat@americoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/27/2013 Phone: 713-984-9700	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**NOVEMBER 3rd 2013**

*2RP-1963*