

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

NJMW1329034197 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <u>269324</u>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: HE West B 10	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 3001505117
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter E	Section 09	Township 17S	Range 31E	Feet from the 1980	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.85087 Longitude: -103.88039

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls	Volume Recovered: 0
Source of Release: Fiberglass pipeline	Date and Hour of Occurrence: 10/14/2013 12:00pm	Date and Hour of Discovery: 10/14/2013 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 10/16/2013 7:15am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: Found location of injection line leak which had put injection out of service in area. Spill composed of fresh and produced water. Approx 20 barrels total fluid. Were using pump truck with fresh water at time to find location of leak.		
Describe Area Affected and Cleanup Action Taken.*: spill located across road to North East about 200 ft from well next to cattle guard.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: Signed By	
Title: Construction Foreman II	Approval Date: OCT 17 2013	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval: Remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 10/16/2013 Phone: 806-367-0645	PROPOSAL NO LATER THAN: November 17, 2013	

* Attach Additional Sheets If Necessary

2RP-1995