


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87716
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1333031416

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-387H, the spill location is 1.42 miles N.W. of the well location.	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41185
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	12	25S	30E					Eddy

Latitude N 32.14954 Longitude W 103.84270

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 65 Bbls	Volume Recovered: 15 Bbls
Source of Release: 8" Frac Hose	Date and Hour of Occurrence: 11/18/13 at approximately 3:10 p.m.	Date and Hour of Discovery: 11/18/13 at 3:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and BLM "Jim Amos"	
By Whom? Tony Savoie	Date and Hour 11/18/13 at 3:51 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.*
The 8" flat line was being used to transfer produced water from the Harrison SWD to the PLU-387H for frac water. The line had a small damaged area near one of the Victaulic connections. The affected area was cut out and a sleeve was clamped in place.

Describe Area Affected and Cleanup Action Taken.*
A vacuum truck was standing by during the frac operations and used to recover approximately 15 bbls of water, the spill affected an area in the pasture of approximately 1600 sq.ft. This area is directly on top of a buried 4" poly salt water disposal line operated by BOPCO. Basin environmental issued a one-call and began clean-up operations on 11/19/13. The spill area will be remediated in accordance to the NMOCD and BLM requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By <i>Mike Scanlon</i>	
Title: Waste Management and Remediation Specialist	Approval Date: NOV 26 2013	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 11/20/13	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
December 26, 2013

2RP-2077