

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 21 2013

Form C-141
Revised August 8, 2011

NMOC District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NJMW 13199 32108

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating 269 324	Contact: Brian Wall
Address: 2130 W. Bender, Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B North Battery - Turner B 95 2RP-1733	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Unknown	API No. 30-015-28465
------------------------	------------------------	----------------------

LOCATION OF RELEASE

30-015-26612

Unit Letter L	Section 20	Township 17S	Range 31E	Feet from the 2610	North/South Line South	Feet from the 1000	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.819971 Longitude 103.897239

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 60 bbls	Volume Recovered: 50 bbls
Source of Release: Tank	Date and Hour of Occurrence: 07/13/2013 8:00 am	Date and Hour of Discovery: 7/13/2013 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton - BLM Mike Bratcher - NMOCD	
By Whom? Gary Wink	Date and Hour: 7/15/2013 8 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		

Describe Cause of Problem and Remedial Action Taken.*
7-12-2013 cleaned out tank #4, moved 60 bbls of production over to tank #1. 7-13-13 Pulled up to battery, seen oil tank #1 leaking from the bottom.
Called vac truck to pick up stand fluid.

Describe Area Affected and Cleanup Action Taken.*
Spill affected a 15' x 20' area within the earthen containment. The facility was temporarily dismantled, and the entire battery was excavated to 4 ft below ground surface. All earthen berms and the underlying soils were removed, expanding the excavation at least 10 ft in each direction from the center to the north, east, and west. Impacted soils were removed to a NMOCD approved disposal facility. Soil samples were collected via drill rig and were submitted to a commercial lab for chloride, TPH, and BTEX analyses. A 20 mil reinforced plastic liner was installed at 4 ft. The excavation was backfilled with clean soil and caliche. The site was compacted and leveled. A poly lined containment system was installed in place of the formerly bermed area and the battery was reconstructed within the new containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Brian Wall	Approval Date: 12/4/13	Expiration Date: N/A
Title: Construction Foreman II	Conditions of Approval: N/A <i>[Signature]</i>	
E-mail Address: bwall@linenergy.com	Attached <input type="checkbox"/>	
Date:	Phone: 806-367-0645	

* Attach Additional Sheets If Necessary

2RP-1733