

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 30 2013

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC
NMOCD ARTESIA

Release Notification and Corrective Action

NTM/1400848180

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: J L Keel A #10	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05098
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter I	Section 07	Township 17S	Range 31E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.84728 Longitude: -103.90176

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 200 bbls	Volume Recovered: 0
Source of Release: Fiberglass pipeline	Date and Hour of Occurrence: 12/27/2013 2:00pm	Date and Hour of Discovery: 12/27/2013 2:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher-NM OCD	
By Whom? Joe Hernandez	Date and Hour 12/27/2013 3:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Mario Hernandez, called me told me that line #3 at Keel West injection was going down on low discharge pressure. We went to chasing lines out to find leak, found leak 500 feet south of Keel A. #10 well. Shut line in. Waiting on one call to clear to repair and clean up spill.

Describe Area Affected and Cleanup Action Taken.*: Legals for spill are. 32.5045N 103.5410 W. Spill runs 300 feet south, 15 to 50 feet wide, then goes south west 1650 feet. 20 feet wide. legals at end of spill are. 32.5035 N 103.5421 W. @" fiber glass line blow in two pieces.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor Signed By 	
Title: Construction Foreman II	JAN 08 2014 Approval Date:	Expiration Date:
E-mail Address: bwall@linenergy.com Date: 12/30/2013 Phone: 806-367-0645	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

REMEDIAL ACTION
PROPOSAL NO LATER THAN:

February 3, 2014

2RP-2142