


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMW1402129082

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ South Water Distribution Site	Facility Type	SWD

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-10756
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	17S	29E					Eddy

Latitude 32.81215 Longitude 104.07706

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10bbls of oil 30bbls of produced water	Volume Recovered	8bbls of oil 28bbls of produced water
Source of Release	Water tank	Date and Hour of Occurrence	12-24-2013	Date and Hour of Discovery	12-24-2013 12:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	12-26-2013 07:34am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Suction valve was not open. Make sure all suction valves are open.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of oil were released and 30bbls of produced water were released due to a water tank that over flowed. We were able to recover 8bbls of oil and 28bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: Signed By	
Title: Senior Environmental Coordinator		Approval Date: JAN 21 2014 Expiration Date:	
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 01-02-2014 Phone: 432-661-6601		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Accepted for record
NMOCD

2RP-2149