

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 20 2013

Form C-141
Revised August 8, 2011

Submit 1 copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1400255460

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	873	Contact Bruce Baker
Address 8 Ellison Lane Eunice, NM 88231		Telephone No. (432) 631-6982
Facility Name Tony Federal Battery		Facility Type Battery

Surface Owner BLM	Mineral Owner	API No. 30-015-30244
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter K	Section 18	Township 17S	Range 31E	Feet from the 1385'	North/South Line FSL	Feet from the 1510'	East/West Line FWL	County Eddy
---------------	------------	--------------	-----------	---------------------	----------------------	---------------------	--------------------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 25 barrels (20 barrels of water and 5 barrels of oil)	Volume Recovered 20 barrels (17 barrels of water and 3 barrels of oil)
Source of Release Water Tank	Date and Hour of Occurrence 12/15/2013 at 8:00 a.m.	Date and Hour of Discovery 12/15/2013 at 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (NMOCD) and Jeffery Robertson (BLM)	
By Whom? Bruce Baker	Date and Hour 12/16/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Transfer pump went down due to a loose coupling causing the water tank to overflow. Pump was repaired and vacuum truck was dispatched to collect fluid from release area.

Describe Area Affected and Cleanup Action Taken.*

The release area was contained inside the bermed area. A vacuum truck was dispatched and recovered 20 barrels of total fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>	
Title: Environmental Technician	Approval Date: AN 02 2014	Expiration Date:
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 12/20/2013	Phone: (432) 631-6982	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
February 2, 2014

2RP-2132