District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr. Santa Fe. NM 8750

State of New Mexico Energy Minerals and Natural Resources

RECEIVED

DEC 19 2013

NMCSUBMITA COPYEGappropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.

1220 S. St. Frag	ncis Dr., Santa	Fe, NM 8750	5	Sa	inta F	e, NM 875	505					
TN			Rela	ease Notifie	catio	n and Co	orrective A	ction		<u></u>		
		49936				<b>OPERA</b>			ial Report	🔲 Final	Report	
Name of Company Oxy Permian Ltd. 16696						Contact Chancey Summers						
Address 1017 W. Stanolind Rd, Hobbs, NM 88240 Facility Name Cedar Canyon 28 Federal Com #2H						Telephone No. (575) 397-8216   Facility Type Well						
						Facility 1 yr	e Well					
Surface Owner BLM Mineral Owne							<u></u>	API N	API No. 30-015-41073			
	Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County											
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/West Line	County ·			
В	28	245	29E	458		North	1980	East	Eddy Cou	nty, NM		
•				Latitude		Longit	ude	_				
				NAT	<b>URE</b>	OF REL	EASE					
Type of Release Oil						Volume of			Volume Recovered			
Source of Release A valve was left open on a frac tank						15 bbls Date and H	lour of Occurrence	0 bbls e Date and	0 bbls Date and Hour of Discovery			
						12/07/2013						
Was Immediate Notice Given?						If YES, To Whom? d Mike Bratcher-NMOCD; Jennifer Van Curen- BLM						
By Whom? Rachel McPherson						Date and Hour 12/10/2013 @ 9:18 am						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
If a Watercou	100 1100 lm						·			••••••••••••••••••••••••••••••••••••••		
If a watercol	arse was imp	acteu, Desch	be runy."	-							1	
	•											
Describe Cause of Problem and Remedial Action Taken.*												
A valve on a	frac tank wa	s left open ca	using 15 t	bls of oil to lcak	onto the	e ground. No	fluids were recov	ered and the valv	e was closed.		l	
Describe Area	a Affected a	nd Cleanup A	ction Tak	en.*						······································		
The affected	area is appro	ximately 30'	x 50' on l	ocation. Remedia	tion wi	ll be complete	d in accordance	with a remediation	n plan approv	ed by NMOC[	D and	
the BLM.							-					
I hereby certit	fy that the in	formation giv	en above	is true and compl	ete to th	e best of my	knowledge and u	nderstand that put	suant to NM	CD rules and		
regulations al.	or the enviro	re required to mment. The	ereport and	d/or file certain re e of a C-141 repo	lease no t by the	stitications an NMOCD ma	d pertorm correct rked as "Final Re	tive actions for re	eases which lieve the oper	may endanger ator of liability		
should their o	perations ha	ve failed to a	dequately	investigate and re	mediate	e contaminatio	on that pose a three	eat to ground wate	r, surface wa	ter, human hea	ilth	
or the environ federal, state,	ment. In ad	dition NMO	CD accept ations	ance of a C-141 r	eport de	oes not relieve	the operator of r	esponsibility for o	compliance w	ith any other		
		$\rightarrow$	><	<u> </u>			OIL CONS	SERVATION	DIVISIC	N		
Signature:									A			
						Approved by Environmental Specialist By Mile Bernarden						
Printed Name	: Chancey	Summers					0.0.0011					
Title: HES	Specialist					Approval Date	N 02 2014	Expiration	Date:			
E-mail Addres	ss: <u>Chance</u>	ry.Summers@	<u>doxy.com</u>	•		Conditions of	Approval:			<b>—</b> .		
Data: 12	19.1	}	Dhann	((75) 207 0214		Remediation per OCD Rule & Guidelines, & Attached						
Date: 12 17 Phone: (575) 397-8216 Attach Additional Sheets If Necessary 79 9 - 212										2120	l	
							PROPOSAL NO LATER THAN: 2RP-2130					
						Fess.	<u> </u>	17	:			