

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 12 2014

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n HMP 1406640288

Name of Company <i>J CLEO THOMPSON 11181</i>		Contact <i>JOHN HUGHES</i>
Address		Telephone No. <i>(432) 661-5313</i>
Facility Name <i>WEST SQUARE LAKE UNIT TRACT 6</i>		Facility Type <i>OIL FIELD FLOW LINE</i>
Surface Owner <i>BLM</i>	Mineral Owner <i>BLM</i>	API No. <i>30-015-03993</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>35</i>	<i>16S</i>	<i>30E</i>	<i>550'</i>	<i>N</i>	<i>220'</i>	<i>W</i>	<i>EDDY</i>

Latitude *32.87277* Longitude *-103.95027*

NATURE OF RELEASE

(35 BBLs WATER, 5 BBL OIL)

Type of Release	Volume of Release <i>80 BBLs</i>	Volume Recovered <i>40 BBLs</i>
Source of Release <i>WEST SQUARE LAKE UNIT TRACT 6 TRUNK LINE</i>	Date and Hour of Occurrence <i>2/7/14</i>	Date and Hour of Discovery <i>2/7/14 1430</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>1430 MIKE BRATCHER</i>	
By Whom? <i>SAM BARON SPORT ENVIRONMENTAL SERVICES</i>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

OIL WELL FLUID FLOWING FROM THE WEST SQUARE LAKE UNIT (TRACT 6) TRUNK LINE WAS LEAKING FROM A SMALL HOLE IN THE LINE. LINE WAS REPAIRED AND SPILL WAS CONTAINED IN A LOW AREA APPROXIMATELY 100 YARDS X 10' WIDE.

Describe Area Affected and Cleanup Action Taken.*

VACUUM TRUCK RECOVERED 35 BARRELS OF WATER AND 5 BARRELS OF OIL. SOIL SAMPLES WERE SENT TO THE LAB TO TEST FOR BTEX, TPH & CHLORIDES. EXCAVATOR REMOVED TOP 12" OF CONTAMINATED SOIL AND STOCKPILED ON A LINER. SAMPLING CONTINUES TO DETERMINE DEPTH OF CONTAMINATION.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>SAM BARON</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>DIRECTOR OF EHS SERVICES</i>	Approval Date: <i>3/7/14</i>	Expiration Date:
E-mail Address: <i>sam@sportenv.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>2/11/2014</i> Phone: <i>(432) 352-2753</i>	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

4/7/14

2 RP 2189