

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 15 2014

NMOC D ARTESIA

Form C-141  
Revised August 8, 2011

Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-200 Flow line spill is 3,729 ft. north of the well pad in Section 7	Facility Type: Exploration and Production

Surface Owner: U.S.A.	Mineral Owner: U.S.A.	API No. 30-015-32882
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 7	Township 24S	Range 30E	Feet from the 1960	North/South Line North	Feet from the 533	East/West Line East	County: Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	-----------------

Latitude N 32.234011 Longitude W 103.914056

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 2 bbls crude oil and 3 bbls produced water	Volume Recovered: None
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 1/5/14 time unknown	Date and Hour of Discovery: 1/5/14 at 8 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flow developed a leak due to corrosion. The section of flow line was replaced.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 1,668 sq.ft. of pasture was impacted by the release. The area had been recently disturbed by pipeline activity. All of the fluid soaked into the ground.

The impacted area will be remediated in accordance to the NMOCD and BLM recommended guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Tony Savoie	Approved by Environmental Specialist: Signed By M/L Brannon	
Printed Name: Tony Savoie	Approval Date: JAN 28 2014	Expiration Date:
Title: Waste Management and Remediation Specialist	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
E-mail Address: tasavoie@basspet.com	Attached <input type="checkbox"/>	
Date: 1/14/14	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:  
February 28, 2014

2RP-2163