


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*24MP1409228272*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <i>Burnett Oil Co. Inc.</i>		Contact <i>Belton Mathews</i>	
Address <i>801 Cherry Street, Fort Worth, TX 76102</i>		Telephone No. <i>817-332-5108</i>	
Facility Name <i>Gissler B 2 Battery</i>		Facility Type <i>Battery</i>	
Surface Owner <i>BLM</i>	Mineral Owner <i>BLM</i>	API No. Lease # <i>NMNM2748</i>	

**LOCATION OF RELEASE**

Unit Letter <i>I</i>	Section <i>23</i>	Township <i>17S</i>	Range <i>30R</i>	Feet from the <i>NE1/4SE1/4</i>	North/South Line	Feet from the	East/West Line	County <i>EDDY</i>
-------------------------	----------------------	------------------------	---------------------	------------------------------------	------------------	---------------	----------------	-----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <i>Petroleum/Water Mix</i>	Volume of Release <i>Minimal Spray</i>	Volume Recovered <i>None</i>
Source of Release <i>Faulty Fire Tube Gasket</i>	Date and Hour of Occurrence <i>1/22/2013 2:30am</i>	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <i>Night Watchman, Staff Responded</i>	Date and Hour <i>1/22/2013 3:00am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
*Faulty Fire Tube Gasket. Switched to test heater in order to replace fire tube gasket.*

Describe Area Affected and Cleanup Action Taken.\*  
*See attached work plan.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Leslie Garvis</i>		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Regulatory Coordinator</i>		Approval Date: <i>4-2-14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>lgarvis@burnettoil.com</i>		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>1/27/14</i>	Phone: <i>817-332-5108</i>		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:**

*5-2-14*

*2RP-2242*