

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1407130197

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Indian Flats Bass Federal SWD Tank Battery Battery is located 2996 ft. S.W. of Well #1 API 30-015-24968	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-24968

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
J	35	21S	28E	1652	South	2150	East	

Latitude N. 32.433935 Longitude W. 104.055036

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 153 Bbbs.	Volume Recovered: Total 138 Bbbs. 110 bbls from the 0 perm cont. 28 bbls. off the ground.
Source of Release: 1" fitting on the SWD pump	Date and Hour of Occurrence: Date 2/10/14 time unknown	Date and Hour of Discovery: Date 2/10/14 at 9:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104	
By Whom? Jody Walters	Date and Hour: 2/10/14 at 3:02 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A one inch fitting on the SWD pump broke during the night. The pump was shut down and the failed fitting was replaced.

Describe Area Affected and Cleanup Action Taken.* The SWD pump and tank battery have been fitted with 0 perm containment, the high pressure spray was not completely contained, an area covering approximately 3080 sq.ft. in front of the SWD was impacted by the release. This area had been impacted by several releases in the past. All previous spills were remediated and a closure request was submitted on 10/3/13. The area impacted this time may have an environmental liner in place approximately 3 ft below ground surface. The spill area will be remediated in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <i>3/12/14</i>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 2/18/14	Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4/12/14

2 RP 2198