

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87401
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

MAR 17 2014

NMOCD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP 1407733945		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. 260373		Contact: Tony Savoie			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: Golden "D" Federal #4		Facility Type: Exploration and Production			
Surface Owner: USA		Mineral Owner: USA		API No. 30-015-35636	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
I	17	21S	29E	2310	South	330	East	Eddy

Latitude N 32.478527 Longitude W 103.999193

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 1 bbl crude oil and 10 bbls produced water	Volume Recovered: 1 bbl produced water
Source of Release: Connection on casing choke	Date and Hour of Occurrence 3/6/14 time unknown	Date and Hour of Discovery 3/6/14 at 9:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



The casing choke developed a leak. The well was shut in, closed all valves and bled down pressure in a vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

The release impacted approximately 4300 sq.ft. of well pad area, based on conditions observed at the time of the site assessment and review of aerial photos, this spill is nearly directly on top of a previous spill at the well location. All of the free standing fluid was recovered. The spill area was left intact pending remediation activities.

The pad area will be cleaned in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist		Approval Date: 3-18-14	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 3/17/14 Phone: 432-556-8730		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4-18-14

2RP-2218