

Hobbs, NM 88240

Avenue, Artesia, NM 88210

Brazos Road, Aztec, NM 87410

10 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 32 State #003H	Facility Type	Flowline
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-41642

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	25S	28E					Eddy

Latitude 32 05.660 Longitude 104 07.012

**NATURE OF RELEASE**

Type of Release	Volume of Release	Volume Recovered
Produced water	18bbbls	17bbbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Poly flowline	01-17-2014	01-17-2014 4:20pm
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		
By Whom?	Date and Hour	<b>NM OIL CONSERVATION</b> ARTESIA DISTRICT
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

JUN 09 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\*

Poly crew cut into the line and squeezed off both ends. The water transfer pump kicked on building up pressure until the clamp on the upstream side failed. Shut down transfer pump and fused the line back together.

Describe Area Affected and Cleanup Action Taken.\*

Initially 18bbbls of produced water were released. We were able to recover 17bbbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michelle Mullins</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Michelle Mullins	Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Coordinator	Approval Date: <i>6/4/14</i>	Expiration Date: <i>NA</i>
E-mail Address: mmullins@concho.com	Conditions of Approval: <i>Final</i>	
Date: 06-06-2014 Phone: 432-934-1052	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*2RP-2202*