

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

7AB1421036589 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU-JV-CVX-Big Sinks #017H AKA PLU Big Sinks 7-25-31 USA #1H Area 2	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40447

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	25S	31E					Eddy

Latitude N 32.151831 Longitude W 103.818964

NATURE OF RELEASE

Type of Release: Crude Oil and produced water	Volume of Release: 12 bbls. water and 8 bbls. crude oil	Volume Recovered: None
Source of Release: Free Water Knockout Sight glass	Date and Hour of Occurrence: Prior to 6/17/14	Date and Hour of Discovery: 6/17/14 at 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

NM OIL CONSERVATION
ARTESIA DISTRICT

If a Watercourse was Impacted, Describe Fully.*

JUL 18 2014

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED

The release area was discovered by a BOPCO Lead Pumper. It appeared that the sight glass had been broken and repaired.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 900 sq. ft. of tank battery pad. The release also misted approximately 4500 sq. ft. of pasture area that had been cleared of vegetation during the tank battery pad construction.
The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: H. Savoie	
Title: Waste Management and Remediation Specialist		Approval Date: 7/29/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines and like	
Date: 7/18/14 Phone: 432-556-8730		Approval by B.L.M. <input type="checkbox"/> Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/29/14

RP2-2402