



District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1423227481 OPERATOR Initial Report Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Maverick 13 DM Fed Com #1H	Facility Type: Producing Oil Well
Surface Owner: Private	Mineral Owner: BLM
API No. 30-015-42089	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	13	24S	26E	185'	North	660'	West	Eddy

Latitude 32.224098 Longitude -104.25299

NATURE OF RELEASE

Type of Release: Produced water(60bbls)/Oil(20 bbls)	Volume of Release: 80 bbls	Volume Recovered: 40 bbls PW 20 bbls Oil
Source of Release: Oil Tank	Date and Hour of Occurrence 8-16-14	Date and Hour of Discovery 8-16-14 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom? Zack Thomas	Date and Hour 7-23-14 12:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Dump on separation equipment hung open sending high volume of gas and fluid to production tank causing tank to run over. Upon pumper arrival well was shut-in at the well head to stop the release.

Describe Area Affected and Cleanup Action Taken.*
Affected area- Inside metal secondary containment (2-4in. standing fluid). 100 ft by 120 ft area affected outside containment in-between pumping unit and tanks. 300 ft by 200ft area of pasture south of well pad was affected by oil mist and will be micro blazed. Produced water and oil was sucked out by vacuum truck (about 80 barrels recovered) and put back into water tank. Steamer will clean tanks, cat walk, separation equipment, and secondary containment. The contaminated soil outside the containment will be dug out and hauled off. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist	
Title: Environmental Rep.	Approval Date: <u>8/20/14</u>	Expiration Date: <u>NA</u>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Remediation per OCD Rule 8	Attached <input type="checkbox"/>
Date: 8-19-14	Phone: 575-602-2188	Guidelines. SUBMIT REMEDIATION

* Attach Additional Sheets If Necessary
PROPOSAL NO LATER THAN:
9/20/14 **2RP2447**