


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company Devon Energy 15025	Contact	
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 748-3371	
Facility Name Apache 24-3 Battery	Facility Type Oil	
Surface Owner	Mineral Owner	API No. 30-015-28016

LOCATION OF RELEASE

Unit Letter A	Section 24	Township 22S	Range 30E	Feet from the 680	North/South Line North	Feet from the 405	East/West Line East	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: _____ Longitude: _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 200	Volume Recovered 160
Source of Release Punctured water transfer line	Date and Hour of Occurrence February 11, 2014; 1:30pm	Date and Hour of Discovery February 11, 2014; 4:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jerry Mathews; Don Mayberry; Amancio Cruz Mike Bratcher-OCD/Jim Amos-BLM	
By Whom? Wes Ryan/Hub Perry	Date and Hour February 11, 2014; 4:15pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

At the Apache 24-3 battery a produced water transfer line was punctured when it was run over by a water truck causing it to spill down the road. Flow back drivers did not report the leak and the pumper had yet to make it to that section of his route for the day. A WIPP employee discovered the spill and contacted assistant foreman Wes Ryan who called the Lease Operator who then he went directly to the site and began to shut in the surrounding wells. When the lease operator realized that is was his transfer pump that was producing the leak he turned that off as well and immediately called for recovery trucks who started with cleanup and had roustabouts come out and repair flow line.

Describe Area Affected and Cleanup Action Taken.*

Spill flowed into a ditch approximately 1/4 mile down the road. Roustabouts were called in to begin cleanup and recovery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Veronica Teel	OIL CONSERVATION DIVISION	
Printed Name: Veronica Teel	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 3/12/14	Expiration Date: NA
E-mail Address: Veronica.Teel@dvn.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: February 13, 2014	Phone: 575-748-9933	


* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4/12/14

2RP 2200

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87401
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP 140 7141448		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy		Contact		
Address PO Box 250 Artesia, NM 88211		Telephone No. 575-748-3371		
Facility Name Apache 24-3 Battery		Facility Type Oil		
Surface Owner		Mineral Owner	API No. 30-015-28016	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	22S	30E	680	North	405	East	Eddy

Latitude: ___ Longitude: ___

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 200	Volume Recovered 160
Source of Release Punctured water transfer line	Date and Hour of Occurrence February 11, 2014; 1:30pm	Date and Hour of Discovery February 11, 2014; 4:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jerry Mathews; Don Mayberry; Amancio Cruz Mike Bratcher-OCD/Jim Amos-BLM	
By Whom? Wes Ryan/Hub Perry	Date and Hour February 11, 2014; 4:15pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

At the Apache 24-3 battery a produced water transfer line was punctured when it was run over by a water truck causing it to spill down the road. Flow back drivers did not report the leak and the pumper had yet to make it to that section of his route for the day. A WIPP employee discovered the spill and contacted assistant foreman Wes Ryan who called the Lease Operator who then he went directly to the site and began to shut in the surrounding wells. When the lease operator realized that it was his transfer pump that was producing the leak he turned that off as well and immediately called for recovery trucks who started with cleanup and had roustabouts come out and repair flow line.

Describe Area Affected and Cleanup Action Taken.*

Spill flowed into a ditch approximately 1/4 mile down the road. Roustabouts were called in to begin cleanup and recovery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Veronica Teel		OIL CONSERVATION DIVISION	
Printed Name: Veronica Teel		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support		Approval Date: 3/12/14	Expiration Date: NA
E-mail Address: Veronica.Teel@dmn.com		Conditions of Approval:	
Date: February 13, 2014		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
Phone: 575-748-9933		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

4/12/14

2RP 2200