

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NA 1424627897

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Northwest Central Tank Battery	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner:	Lease No. NMNM-86025
------------------------	----------------	----------------------

LOCATION OF RELEASE

API # 30-015-04186

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E	990	South	2310	West	Eddy

Latitude 32.49.813 Longitude 103 59.725

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: Oil: 2 bbls ; PW: 950 bbls	Volume Recovered: Oil: 1 bbls ; PW: 900 bbls
Source of Release: 4" Nipple on collar of water tank	Date and Hour of Occurrence: 8/18/2014 10:30 am	Date and Hour of Discovery: 8/18/2014 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD / Jeffrey Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour: 8/18/2014 4:56 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a corroded 4" nipple on the collar on the water tank. The tank was repaired. Vacuum trucks were dispatched to pick up all standing fluids. All fluids were disposed at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was contained to the bermed area, with no release to the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>9/3/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: August 29, 2014 Phone: 575-748-6940	PROPOSAL NO LATER THAN: <i>10/3/14</i>	

* Attach Additional Sheets If Necessary

2RP-2463