

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
OCT 03 2013
ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No.	(432)556-8730
Facility Name	JRU-29 to Hudson Federal #1 SWD	Facility Type	E&P
The spill was 200 ft. east of the JRU-67 pumping well.			

Surface Owner	State of N.M.	Mineral Owner	State of N.M.	Lease No.	API #30-015-31004
---------------	---------------	---------------	---------------	-----------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	22S	30E					Eddy

Latitude 32.346239° North

Longitude 103.838688° West

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	100 bbls of produced water	Volume Recovered	80 bbls
Source of Release	A buried 2 7/8" SWD line	Date and Hour of Occurrence	8/8/12 Approximately 12:00 pm	Date and Hour of Discovery	8/8/12 Approximately 1:45 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD Emergency #104		
By Whom?	Tony Savoie	Date and Hour	8/8/12 2:57 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken:* The 2 7/8" SWD line from the JRU-29 disposal to the Hudson Federal #1 SWD well developed an internal corrosion leak. The SWD was shut down, and a temporary repair clamp was placed on the affected area of the pipe. The entire line was replaced prior to remediation activities.

Describe Area Affected and Cleanup Action Taken.* Approximately 2250 sq. ft. of pasture land was affected by the release. A vacuum truck was utilized to remove all of the free-standing water from the pooled areas. The area was previously impacted by a produced water spill on 5/22/12. Following initial response activities, both releases were remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Risk-Based Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name:	TONY SAVOIE	Approved by District Supervisor:	<i>[Signature]</i>
Title:		Approval Date:	8/4/12
E-mail Address:		Expiration Date:	NA
Date:	10/3/13	Conditions of Approval:	<i>Final</i>
Phone:			

2RP-1265