

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 03 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

X Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No.	(432)556-8730
Facility Name	James Ranch Unit #29 SWD	Facility Type	E&P

Surface Owner	State of N.M.	Mineral Owner	State of N.M.	Lease No.	API #30-015-27735
---------------	---------------	---------------	---------------	-----------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	22S	30E					Eddy

Latitude 32.346284° North

Longitude 103.837459° West

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	175 bbls of produced water	Volume Recovered	50 bbls
Source of Release	2 7/8" flow line	Date and Hour of Occurrence	5/22/12 Time unknown	Date and Hour of Discovery	5/22/12 9:00 a.m.
Was Immediate Notice Given?	X Yes No Not Required	If YES, To Whom?	NMOCD Emergency #104		
By Whom?	Tony Savoie	Date and Hour	5/22/12 2:30 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to internal corrosion. The SWD pump at the JRU-29 was shut down, and 1 joint of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.* Approximately 3240 sq. ft. of pasture land. All of the free-standing fluid was picked up with a vacuum truck. The spill stayed within the pipeline right-of-way. Following initial response activities, the release was remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Risk-Based Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Tony Savoie</i>	Approved by District Supervisor: <i>[Signature]</i>	
Title:	Approval Date: <i>8/4/14</i>	Expiration Date: <i>NA</i>
E-mail Address:	Conditions of Approval: <i>Final</i>	
Date: <i>10/3/13</i>	Phone:	

2RP-1174