

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

DEC 04 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

### Release Notification and Corrective Action

NAB1433955644

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Unit #18H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-39999
----------------------	----------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	28E	330'	North	330'	East	Eddy

Latitude 32.0488883139878 Longitude -104.102110770708

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 55 bbls	Volume Recovered: 50 bbls
Source of Release: Hole in fire tube	Date and Hour of Occurrence: 11/26/2014 1:30 pm	Date and Hour of Discovery: 11/26/2014 1:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Lupe Carrasco	Date and Hour: 11/28/2014 7:53 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a hole in the fire tube of the heater treater. Repairs were made to the vessel. And vacuum trucks were dispatched to recover standing fluid and dispose of at a NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within the lined bermed area. All fluids were able to be recovered and impacted gravel replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 12/5/14	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 4, 2014 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines.	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 1/5/15

2RP-21460