

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 13 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1501441507

Name of Company: Devon Energy Production Co LP (6137) <i>0137</i>		Contact: Brian Kuh
Address: PO Box 250 Artesia, NM 88211		Telephone No. 575- 616-1540
Facility Name: Cotton Draw 11 Federal #2H		Facility Type: Well location

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-39375
-------------------------------	-------------------------------	-----------------------------

LOCATION OF RELEASE

AKA Cotton Draw Unit 163 H

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	25S	31E	330	North	1980	West	Eddy

Latitude: Longitude: *32.151232*
103.750816

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 bbls	Volume Recovered: 15 bbl
Source of Release: Bosque produced water filtering pod	Date and Hour of Occurrence 01/12/2015, approx. 6:25 A.M.	Date and Hour of Discovery 01/12/2015, approx. 6:25 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jim Amos	
By Whom? Brian Kuh, Foreman	Date and Hour: 01/12/2015; OCD: 2:41 P.M. BLM: 2:44 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On the Cotton Draw 11 Fed 2H, a Bosque employee was changing the filter socks in the dual filter pod when the hose connecting to the KC nipple directly underneath the filter pot disconnected causing the release of approximately 15 barrels of produced water. The hose clamp that holds the hose in place broke causing the pressure of the water to disconnect the hose. The produced water overflowed it's containment (20 ft x 20 ft x 8 in) due to one corner of the containment being lower than the rest, which was caused by an unlevelled surface. Approximately 10 barrels of produced water escaped the containment and on to the pad while another 5 barrels stayed in the containment. The produced water did not leave the pad. Cleanup at the location was started shortly after the release and was completed that day.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck, skid steer, backhoe, and dump truck were all used to clean up the entire spill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Denise Menoud	Signed By <i>Mike Bratcher</i>		
Title: Field Admin Support	Approved by Environmental Specialist:		
E-mail Address: Denise.Menoud@dm.com	Approval Date: <i>1/14/15</i>	Expiration Date: <i>N/A</i>	
Date: 01/13/2015 Phone: 575-746-5544	Conditions of Approval: <i>FINAL</i>		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-2736