

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 2 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1503440420

Name of Company RKI E&P, LLC <i>JALUSA</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 210 Park Ave. - Ste. 900, OKC, OK 73102		Contact Taylor Jones		
Facility Name MWJ Federal I		Telephone No. 405-996-5782		
		Facility Type Oil and Gas Well		

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-24262
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	26S	29E		660 FNL		660 FEL	Eddy

Latitude 32.00346 Longitude -103.94920

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 11Bbls	Volume Recovered 11Bbls
Source of Release Wellhead packing failure	Date and Hour of Occurrence 02/01/15 - Unknown	Date and Hour of Discovery 02/01/15 - 0800hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* **N/A**

Describe Cause of Problem and Remedial Action Taken.*

Wellhead packing failed allowing a mixture of crude oil and produced water to be released; all fluids remained on the well pad. Well shut-in, packing replaced.

Describe Area Affected and Cleanup Action Taken.*

Vacuum truck used to recover free fluid, affected soil back dug and hauled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Taylor Jones</i>	OIL CONSERVATION DIVISION	
Printed Name: Taylor Jones	Approved by Environmental Specialist: <i>Huels</i>	
Title: EHS Systems Specialist	Approval Date: 2/3/15	Expiration Date: N/A
E-mail Address: TJones@rkixp.com	Conditions of Approval:	
Date: 02/02/2015 Phone: 405-996-5782	Remediation per O.C.D. Rules & Guidelines	
SUBMIT REMEDIATION PROPOSAL NO		
LATER THAN: <u>3/3/15</u>		

Attached

* Attach Additional Sheets If Necessary

2RP-2183