

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 06 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1504038900

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill		
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077		
Facility Name: USP Fee #2H	Facility Type: Battery		
Surface Owner: Fee	Mineral Owner: Fee	API No. 30-015-34438	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	23S	29E	319	North	946	West	Eddy

Latitude 32.3115855749959 Longitude -103.995165081777

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 170 bbls Oil	Volume Recovered: 170 bbls Oil
Source of Release: Pump	Date and Hour of Occurrence: 2/5/2015 8:00 am	Date and Hour of Discovery: 2/5/2015 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 2/6/2015 4:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by the Victaulic clamp and psi gauge leaking on a circulating pump. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred with the lined facility. All fluids were able to be recovered and repairs made.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: <i>A Trujillo</i>	Signed By: <i>M. Bratcher</i> Approved by Environmental Specialist:
Printed Name: Amanda Trujillo	Approval Date: <i>2/9/15</i> Expiration Date: <i>N/A</i>
Title: Senior Environmental Coordinator	Conditions of Approval: <i>FINAL</i> Attached <input type="checkbox"/>
E-mail Address: <i>atrujillo@concho.com</i>	
Date: February 6, 2015 Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

2RP-2794