

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
DEC 21 2011
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No.	(432)556-8730
Facility Name	Remuda Basin 25 State #1	Facility Type	E&P
Surface Owner	State of N.M.	Mineral Owner	State
		Lease No.	E5894

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	25	23S	29E					Eddy

Latitude 32.288041° North **Longitude** 103.936333° West

NATURE OF RELEASE

Type of Release	Produced water and condensate	Volume of Release	95 bbls of produced water and less than 1 bbl condensate	Volume Recovered	None
Source of Release	300 bbl produced water tank	Date and Hour of Occurrence	6/4/44, between 5 pm and 11 pm	Date and Hour of Discovery	6/5/11 9:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Tony Savoie	Date and Hour	6/5/11 7:30 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken:* The 300 bbl water tank was struck by lightning the evening of 6/4/11, the pumper discovered it the next morning, all of the water had soaked into the ground inside the earthen containment. There was no evidence of fire anywhere at the facility. The well was shut in the morning of 6/5/11.

Describe Area Affected and Cleanup Action Taken.* Approximately 2100 sq. ft. inside the containment area and approximately 300 sq. ft. outside the containment area on the caliche well pad. Following initial response activities, the release was remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name:	Tony Savoie	Approved by District Supervisor:	<i>[Signature]</i>
Title:	Waste Mgmt. & Remediation Specialist	Approval Date:	1/14/15
E-mail Address:	TASavoie@BassPet.com	Expiration Date:	NA
Date:	12/6/2011	Conditions of Approval:	<i>Final</i>
Phone:	(432)556-8730		

2RP-821