

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	600 W. Illinois Avenue, Midland, TX 79701	Telephone No.	(432) 230-0077
Facility Name	Santa Elena 19 Federal #001H	Facility Type	Tank Battery

Surface Owner: Federal	Mineral Owner	Lease No. (API#) 30-015-40567
------------------------	---------------	-------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	16	19S	30E					Eddy

Latitude N 32.90989° Longitude W 104.01856°

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release 40 bbls	Volume Recovered 30 bbls
Source of Release: Open valve on a load line to water tank	Date and Hour of Occurrence 02/21/2013	Date and Hour of Discovery 02/21/2013 7:00 a.m.

Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher—OCD</b>
--	--

By Whom? Michelle Mullins	Date and Hour 03/4/2013 10:01 a.m.
---------------------------	------------------------------------

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A
---	--

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The truck driver left the valve open on a load line to the water tank. Shut valve on the load line to prevent further release of produced water.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech personnel inspected the site and collected samples to define the spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ike Tavarez (Agent for COG)	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 9/9/11	Expiration Date: N/A
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: <b>Final</b>	
Date: 10-25-13 Phone: (432) 682-4559	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

288-1578